

### Legend

Bound Brook Centerline (RM) Dams (Natural and Manmade) Pipes Crossing the Brook Shoreline Former Cornell Dublier Electronics Facility T1-A Sample Location ID

# Panel A

#### Texture

Fine Sand

0 Silt

Coarse Sand O Silt with Clay O Coarse to Fine Sand

Clay with Silt Coarse to Medium Sand Cobbles Medium to Fine Sand

Gravel

Hard Bottom

## **New Market Pond**

Sand as interpreted by the side scan sonar

Rock-Gravel-Sand as interpreted by the side scan sonar Silt as interpreted by the side scan sonar

### Panel B

Depth to Refusal (ft.)

Depth Advanced
Without Refusal\* (ft.)

•	0.0 - 1.0		0.0 - 1.0	
0	1.1 - 2.0		1.1 - 2.0	
0	2.1 - 3.0		2.1 - 3.0	
0	3.1 - 4.0	$\triangle$	3.1 - 4.0	
0	4.1 - 5.0		4.1 - 5.0	
•	> 5.1		5.1 - 6.5	


\*Probe rod not long enough to accommodate water depth and to encounter refusal.


### Sources:

- 1) Background Data Street Information, NJDOT, 2012; Streams, NJDEP, 2002.
- 2) Shoreline was adapted from a Tetra Tech, Inc. shoreline shapefile, which was adjusted to be consistent with information collected in the field, aerial imagery provided by Penoni Associates, Inc., and 2002 aerial imagery from the New Jersey Office of Information Technology (Office of GIS).
- 3) "Hard bottom" is a generic term that covers all types of hard material that the probe rod could not penetrate (e.g., cinderblocks, rip-rap, bedrock, rock, or hard debris). Only exposed bedrock at the surface can be visually identified and confidently classified as "weathered, fractured bedrock."



KEY MAP
Sediment Probing Interpretation
Bound Brook OU4 RI/FS






Sediment Probing Interpretation

Panel A: Surface Sediment Texture and Panel B: Depth of Refusal


Bound Brook OU4 RI/FS

Figure 3-2 Sheet 3 of 11



Sediment Probing Interpretation
Panel A: Surface Sediment Texture and Panel B: Depth of Refusal
Bound Brook OU4 RI/FS

Figure 3-2 Sheet 4 of 11






Sediment Probing Interpretation
Panel A: Surface Sediment Texture and Panel B: Depth of Refusal
Bound Brook OU4 RI/FS


2014


Figure 3-2 Sheet 5 of 11



Sediment Probing Interpretation
Panel A: Surface Sediment Texture and Panel B: Depth of Refusal
Bound Brook OU4 RI/FS

Figure 3-2 Sheet 6 of 11








Sediment Probing Interpretation
Panel A: Surface Sediment Texture and Panel B: Depth of Refusal

Bound Brook OU4 RI/FS


Figure 3-2 Sheet 8 of 11



South Plainfield, New Jersey


Sediment Probing Interpretation
Panel A: Surface Sediment Texture and Panel B: Depth of Refusal
Bound Brook OU4 RI/FS


Figure 3-2 Sheet 9 of 11



Sediment Probing Interpretation
Panel A: Surface Sediment Texture and Panel B: Depth of Refusal
Bound Brook OU4 RI/FS

Figure 3-2 Sheet 10 of 11







2011-2013 RI Sediment and Soil Sampling Location Identification

Bound Brook OU4 RI/FS Bound Brook OU4 RI/FS

Sheet 1 of 6






L B Cornell-Dubilier Electronics
Superfund Site
South Plainfield, New Jersey


2011-2013 RI Sediment and Soil Sampling Location Identification


Bound Brook OU4 RI/FS

Figure 3-3 Sheet 3 of 6





Sheet 4 of 6





Sheet 6 of 6






THE Louis Berger Group, INC.


DRAFT FINAL

2014


3-4b




CORNECE-TOF - LBG.601 -





-




THE Louis Berger Group, INC.











2014

3-4i


THE Louis Berger Group, INC.




CORNELL-TOP - LBG.GDT - 10/17/12 17:25 - C:\USI





CORNELC-1 OF - LBG. GD1 - 10/23/12 11.31 -





























Figure 3-11